

Lycoming O540, Failed Pushrod Shroud Springs, ATA 8530

A technician states, "Tracing an oil leak, it was discovered the pushrod shroud tube retaining springs (SL14995) had failed on all six cylinders. The part failed by breaking into two or more fragments. This allowed the shroud to unseat from the head and leak oil. All six springs were replaced." *(There are eight similar reports in the SDRS database.)*



Part Total Time: Unknown