

## Univar 415-C, Sheared Brake Clevis, ATA 3240

"On landing," says this general aviation technician, "*(this aircraft)* lost braking action. An investigation found the brake piston clevis rod—between the brake pedal arm and the master cylinder—had sheared below the lock nut."

*(Piston clevis rod P/N: 4008. Component name and P/N: Brake Arm; 41533458. See photo below.)*



Part Total Time: 617.0 hours

