


## Beechcraft 200, Cracked Spar Shear Fitting, ATA 5740

"While accomplishing a wing bolt inspection," says this unidentified technician, "the L/H lower wing spar attach shear fitting was found cracked (P/N 1011100731). This crack is approximately 0.75 inches long and is located in the forward flange area."



**Beechcraft 200, Cracked Spar Shear Fitting, ATA 5740**



Part Total Time: 13,141.0 Hours