Piper PA34-200, Cracked Nose Gear Trunnion, ATA 3222

A repair station mechanic states, "(During) an Annual inspection, (I) found the right pivot point of the nose gear trunnion cracked (at the point...) where the trunnion is welded to the pivot bolt housing." (Trunnion

P/N: 9572300. This part is referenced at least four times in the SDRS database.)



Piper PA34-200, Cracked Nose Gear Trunnion, ATA 3222



Part total Time: 4,547.0 Hours