

Piper PA46-500TP, Nose Gear Torque Link Missing Bolt, ATA 3220

A general aviation report states, "The aircraft owner/pilot noticed a vibration shortly after landing. Inspection of the nose landing gear assembly found the bolt, nut, washer, and cotter key missing from the center torque link, and the tire was lightly flat-spotted." (*Torque Link Component P/N: 106680002.*)

Part Total Time: 132 Hours