

Bombardier BD100-1A10, Defective Tire, ATA 3244

A commercial operator's technician stated, "A bulge on the number two main tire (P/N 269K43-2) outer sidewall is consistent with bulges found on previous tires (P/N 269K43-1). This tire is being sent to Goodyear for evaluation."



Bombardier BD100-1A10, Defective Tire, ATA 3244



Part Total Time: 450 Hours (192 Cycles)