


**Beechcraft B200, Cracked Spar Attach Fitting, ATA 5740**

A general aviation submitter states, "While accomplishing a wing bolt inspection, the L/H lower wing spar attach shear fitting was found cracked (P/N 1011100731). This crack is approximately 0.75 inches long—located in the forward flange area."



**Beechcraft B200, Cracked Spar Attach Fitting, ATA 5740**



**Beechcraft B200, Cracked Spar Attach Fitting, ATA 5740**



Part Total Time: 13,141.0 Hours