

## **Aviat A1, Blocked Fuel Vent Lines, ATA 2801**

An unidentified submitter advised that both fuel vent lines were blocked by ice. The engine stopped during its taxi to the runway. The writer noted the preflight check list did include confirming these vent lines are free of obstructions, but suggested there should be more emphasis placed on this 'before flight' inspection criterion.

*(P/N's were not included with this report, but this particular vent line is described as the one routed from the tank out to the wingtip.)*

Part Total Time: (unknown).