

Beech A36, Loose Auto Pilot Connecting Rod

A submitter writes, "The auto-pilot hook-up rod should be tightened up or removed from the aircraft at the factory. This is the second aircraft in one week (*in which*) this rod (*and/or its attachment nuts*) has been found loose...." (*Elevator control bell crank P/N: 002-524024-51.*)

Beech A36, Loose Auto Pilot Connecting Rod



Part Total Time: 140.0 hours.