


Beech F33A, Cracked Leading Edge Nose Rib, ATA 5753

An annual inspection found the R/H flap rod attach point rib cracked." (Rib P/N 35-165050-84; Flap P/N 35-165050-606: both the flange and web were found to be cracked.)



Part Total Time: 5,255.1 Hours.