

Modern Risk in Familiar Airplanes - What Part 91 Pilots Miss in Preflight

Modern aircraft with layered avionics, hybrid cockpits, and independent logic paths rarely return to a known baseline following maintenance. Accident data show that configuration errors, not wear and tear, dominate modern post-maintenance events. The first flight should therefore be treated as a validation test flight, not a routine hop. Attendees will learn how subtle configuration errors appear, how to detect them early, and how to structure the first flight for safety margin. The session integrates NTSB and ASRS findings with Airman Certification Standards for Risk Management, Systems and Equipment, and Human Factors to build a practical, take-away recipe for safe validation flights.

Please visit the Orlando Executive Airport FAASTeam Library web site:

<https://www.fsr-inc.org/FAAST/Seminar/Notice.aspx>

Event Details

Thu, May 14, 2026 at 19:00 EDT
Orlando Executive Airport (ORL)
365 Rickenbacker Dr.
Orlando, FL



Contact: Robert Breaux
407-644-4298
FAASTeam@CenturyLink.net
Select #: SO15142946
Lead Representative Robert Breaux n/a

From Colonial Drive turn south on Rickenbacker Dr. Continue through the Fairgreen St intersection to the end of Rickenbacker Dr. and into the parking lot. Park in any available designated spot. Walk east to the Airport Administration Building.

Orlando Executive Airport (ORL)
365 Rickenbacker Dr.
Orlando, FL 32802

A message from the National FAAS Team Manager

Earn your WINGS to get a chance to win a prize. Go to <https://www.wingsindustry.com/WINGS-Sweepstakes> for more info. Join us on Facebook: <https://www.facebook.com/groups/GASafety/>

**Join us on Facebook: <https://www.facebook.com/groups/GASafety/>
Sign up for the FAA's safety services at www.faasafety.gov!**

The FAA Safety Team (FAAS Team) is committed to providing equal access to this meeting/event for all participants. If you need alternative formats or services because of a disability, please communicate your request as soon as possible with the person in the “Contact Information” area of the meeting/event notice. Note that two weeks is usually required to arrange services.