

## **Piper PA28-151 Corroded Wing Attach Fittings, ATA 5341**

### **Piper PA 28-151 Corroded Wing Attach Fittings, ATA 5341**

An unknown submitter writes, This fuselage rear wing attach fitting (P/N 62448-003) was being replaced due to corrosion pits on the front surface. Upon removal, some severe pitting was noted just inboard of the 5/16-inch wing attach bolt hole on the rear side of the fitting.

The area is exposed to outside air and moisture and is located in a difficult area to inspect. This area is also more critical with respect to the eventual part failure than the front surface that remains visible from the inside of the fuselage.:

The submitter recommended cleaning dirt out of this area and inspecting the area with a good light.

Part Total Time: (unknown).