


Powerplant, Continental TSIO 550C1B, Broken Crankshaft, ATA 8520

(The following description involving a Piper PA46-310P doesn't provide speculation or detective work, it does not provide much discussion at all. However, it does include one dramatic photo—Ed.)

"The crankshaft broke," says this mechanic, "just aft of the propeller mounting flange"
(Crankshaft P/N: 649900).



Part Total Time: (unknown).

Powerplant, Continental TSIO 550C1B, Broken Crankshaft, ATA 8520