


Cessna 208B, Cracked Elevator Pulley Support, ATA 5320

Cessna: 208B; Cracked Elevator Pulley Support; ATA 5320

An air operator's submission states, "The left pulley support web below the floor at FS (fuselage station) 120.0 and LBL (butt line) 10.0 cracked—from the left elevator bell crank mount bolt access hole to the end of the web." (Pulley Support P/N: 2613083-1.)

CESSNA AIRCRAFT COMPANY MODEL 208 ILLUSTRATED PARTS CATALOG

A24789



LOWER FORWARD FUSELAGE STRUCTURE
FIGURE 01 (SHEET 5)

53-11-00

Figure 01
Page 8
Jun 1/2010

Cessna 208B, Cracked Elevator Pulley Support, ATA 5320



Cessna 208B, Cracked Elevator Pulley Support, ATA 5320

