

## Cessna C680, Chafed Jet-pump Tubes, ATA 2810

"Extensive fretting damage (*was found*) on the primary jet-pump fittings—and the attaching line fittings where the Wiggins clamps (*W991-18DE*) are installed," writes a repair station mechanic. "Damage occurs to adjacent plumbing—P/N's 6926100-123, 6926100-13 (*and -14, -15, -76*). Damage has been found on Cessna 680 models during tank inspection 28-10-00-201. This condition is dangerous and un-airworthy." (*Primary Jet-Pump P/N: 9914682-1.*)



**Cessna C680, Chafed Jet-pump Tubes, ATA 2810**



Cessna C680, Chafed Jet-pump Tubes, ATA 2810



Part Total Time: (Unknown)

August 2012 AC 43-16A