


Turbomeca, Arriel 2B1, Cracked Turbine Guide Vane, ATA 7250

An AS350B3 helicopter operator writes, "While disassembling the engine to perform modification TU166, (I) found the power turbine nozzle guide vane cracked (P/N 0292517060). The 'Module 3' (P/N 70BM032020) must be returned to the manufacturer for repair."



Part Total Time: 2,590.0 Hours