

## Auxilec Generator, P/N A3579101, Failed Bearing, ATA 2434

(This report references a Bombardier BD1001-A10 aircraft with Honeywell AS90711A engines.)

A technician for a corporate operation says, "The generator rear bearing (opposite drive shaft) failed on the right engine. (Its) mounting pad sheared and the generator split apart. The crew received a 'Generator Fail' CAS (Crew Alerting System) message." There are six of these P/Ns in the SDRS database.)



Total Part Time 1,397.0 Hours