

IMC Club Monthly Meeting EAA Chapter 766

This meeting is led by Tony Kolar, Certified Flight Instructor and Dave Rudd. This seminar is not meant as a lecture but rather an open discussion forum using real world scenarios to increase your level of safety in the IFR environment such as this scenario: **More than Ice.** After about an hour at cruise altitude in IFR condition you start to pick-up lite icing. A few minutes later you hear a loud bang and a crack appears in the wind screen.

To ensure a safe flight your priorities as PIC are to Aviate, Navigate & Communicate. Safe instrument flying is a matter of mitigating risk, personal minimums and standard operating procedures. The Sheboygan Falls (WI) EAA 766 IMC Club provides organized “hangar flying” focused on building proficiency in instrument flying. An instrument rating is not required for attendance.

Event Details

Mon, Sep 7, 2026 at 18:30 CDT

Aviation Heritage Center of Wisconsin

N6191 Resource Dr
Sheboygan Falls, WI



Contact: ANTON JOHN KOLAR

(920) 698-6142

tonyjkolar@gmail.com

Select #: GL13145880

**Representative ANTON JOHN
KOLAR n/a**

IFR Scenario presented by Tony Kolar CFII, Volunteer FAA Safety Representative

Guest instrument pilots and students welcome.

Aviation Heritage Center of Wisconsin Library,
located at the Sheboygan Municipal Airport,
Sheboygan, WI.

A message from the National FAASafety Team Manager

Earn your WINGS to get a chance to win a prize. Go to
<https://www.wingsindustry.com/WINGS-Sweepstakes> for more info. Join us
on Facebook: <https://www.facebook.com/groups/GASafety/>

Join us on Facebook: <https://www.facebook.com/groups/GASafety/>
Sign up for the FAA's safety services at www.faasafety.gov!

The FAA Safety Team (FAASafety Team) is committed to providing equal access to this meeting/event for all participants. If you need alternative formats or services because of a disability, please communicate your request as soon as possible with the person in the "Contact Information" area of the meeting/event notice. Note that two weeks is usually required to arrange services.