

Fuel Engines and Early Warning Signs - Preventing Sudden Power Loss Accidents

Event Details

One of the most preventable accident chains, loss of engine power, is often described as sudden, yet accident data shows most events are preceded by warning signs. This seminar examines fuel and engine related accidents as decision making breakdowns rather than mechanical surprises.

Using NTSB cases and NASA ASRS reports the session highlights how subtle cues such as fuel imbalance, abnormal indications, and shrinking reserves are missed or rationalized. Pilots will learn practical ACS aligned habits for fuel planning in flight, engine trend awareness, and timely diversion decisions that significantly reduce preventable power loss accidents.

Please visit the Orlando Executive Airport FAASTeam Library web site:

<https://www.fsr-inc.org/FAAST/Seminar/Notice.aspx>

Thu, Apr 9, 2026 at 19:00 EDT
Orlando Executive Airport (ORL)
365 Rickenbacker Dr.
Orlando, FL



Contact: Robert Breaux
407-644-4298
FAASTeam@CenturyLink.net
Select #: SO15140912
Lead Representative Robert Breaux n/a

From Colonial Drive turn south on Rickenbacker Dr. Continue through the Fairgreen St intersection to the end of Rickenbacker Dr. and into the parking lot. Park in any available designated spot. Walk east to the Airport Administration Building.

Orlando Executive Airport (ORL)
365 Rickenbacker Dr.
Orlando, FL 32802

A message from the National FAASTeam Manager

Earn your WINGS to get a chance to win a prize. Go to <https://www.wingsindustry.com/WINGS-Sweepstakes> for more info. Join us on Facebook: <https://www.facebook.com/groups/GASafety/>

Join us on Facebook: <https://www.facebook.com/groups/GASafety/>
Sign up for the FAA's safety services at www.faasafety.gov!

The FAA Safety Team (FAASteam) is committed to providing equal access to this meeting/event for all participants. If you need alternative formats or services because of a disability, please communicate your request as soon as possible with the person in the “Contact Information” area of the meeting/event notice. Note that two weeks is usually required to arrange services.